MATERIAL SAFETY DATA SHEET

NPC

SCM CORPORATION
Form 3001 Printed in U.S.A. 5/77

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor Essentially Similar to Form OSHA-20)

DATE OF PREP 3/11/85

Section I

MANUFACTURER'S NAME
SCM - GLIDDEN COATINGS & RESINS DIVISION

STREET ADDRESS
925 EUCLID AVENUE

CITY, STATE, AND ZIP CODE
CLEVELAND, OHIO 44115

EMERGENCY TELEPHONE NO
216-826-5566

PRODUCT CLASS
LATEX PRIMER-SEALER

MANUFACTURERS CODE IDENTIFICATION
Y-5116

TRADE NAME INSUL-AID VAPOR BARRIER - WHITE ★

Section II — HAZARDOUS INGREDIENTS

INGREDIENT	PERCENT	TLV PPM	TLV mg/M³	LEL	VAPO PRESSU
MICA	19		20 mppcf		
TITANIUM DIOXIDE	9		10		
SILICA	3				
DIETHYLENE GLYCOL MONOBUTYL ETHER	1			0.9	0.1
ESTER ALCOHOL	1				

Section III — PHYSICAL DATA

BOILING RANGE 200 TO 212 F.

VAPOR DENSITY [X] HEAVIER, [ ] LIGHTER THAN AIR

EVAPORATION RATE [ ] FASTER [X] SLOWER THAN ETHER

PERCENT VOLATILE BY VOLUME 66.5

WEIGHT PER GALLON 10.7

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY
NOT RESTRICTED

FLASH POINT
> 200°F, TCC

LEL
NONE

EXTINGUISHING MEDIA
CARBON DIOXIDE, DRY CHEMICAL OR FOAM.

UNUSUAL FIRE AND EXPLOSION HAZARDS
CLOSED CONTAINERS MAY BURST IF EXPOSED TO EXTREME HEAT OR FIRE.

SPECIAL FIRE FIGHTING PROCEDURES
NONE REQUIRED.

Section V — HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE NONE ESTABLISHED FOR THIS PRODUCT. SEE SECTION II.

EFFECTS OF OVEREXPOSURE IRRITATION OF EYES, SKIN, AND RESPIRATORY TRACT.

EMERGENCY AND FIRST AID PROCEDURES

FUMES: MOVE PERSON TO WELL VENTILATED AREA.
SKIN CONTACT: WIPE WITH CLEAN CLOTH. WASH THOROUGHLY WITH SOAP AND WATER.
EYE CONTACT: FLUSH THOROUGHLY WITH WATER. GET MEDICAL ATTENTION.
INGESTION: GET MEDICAL ATTENTION IMMEDIATELY.

Section VI — REACTIVITY DATA

STABILITY [ ] UNSTABLE [X] STABLE

CONDITIONS TO AVOID

INCOMPATABILITY (Materials to avoid) NONE KNOWN.

HAZARDOUS DECOMPOSITION PRODUCTS

CARBON MONOXIDE, CARBON DIOXIDE AND POSSIBLE OXIDES OF NITROGEN.

HAZARDOUS POLYMERIZATION [ ] MAY OCCUR [X] WILL NOT OCCUR

CONDITIONS TO AVOID

Section VII — SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

MOP SPILLS WITH INERT ABSORBENT. WASH DOWN AREA WITH WATER.

WASTE DISPOSAL METHOD DISPOSE IN ACCORDANCE WITH ALL APPLICABLE REGULATIONS.
DO NOT INCINERATE CLOSED CONTAINERS.

Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION

USE NIOSH APPROVED RESPIRATOR

VENTILATION

DILUTION VENTILATION USUALLY ADEQUATE.

PROTECTIVE GLOVES OPTIONAL

EYE PROTECTION SAFETY GLASSES OR GOGGLES.

OTHER PROTECTIVE EQUIPMENT

Section IX — SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

KEEP FROM FREEZING. STORE BELOW 100°F.

OTHER PRECAUTIONS

DO NOT TAKE INTERNALLY.
KEEP OUT OF REACH OF CHILDREN.